1 Software

1.1 Compatible modules and software versions

IP DIRECTOR		MULTICAM Compatible package
Routing	05.83.50	
Synchro DB	05.83.50	
IP Drive	05.83.50	
IP Director	05.83.50	
Database	05.82.60	
IP Scheduler	05.83.50	10.02.20
VTR Engine	05.83.50	10.03.39
IP API	05.83.50	
Remote Installer	05.82.50	
User Manager	05.82.50	
Upgrade V4 -> V5	05.21.10	
Software Player	01.04.07	

Upgrade procedure to version 5.8:

- from IPDirector 4.4 : Procedure_Upgrade_IP4_to_5.8.pdf

- from IPDirector 5.6 : Procedure_Upgrade_IP5.6_to_5.8.pdf





1.2 Hardware

1.3 MOXA boards

The MOXA RS422 cards do not fully support all IPDirector 5.8 functionalities. This card is no longer delivered by EVS on IPDirector systems, and customers should consider upgrading the MOXA card to ensure full support and compatibility with this and future IPDirector versions and hardware.

Moxa **cannot be used** to connect to **MPlay** or **BEPlay** series of remotes but remains compatible for XT connections.

1.4 New AVH Driver

The IPDirector version 5.8 is provided with a new AVH driver. This driver is not compatible with older releases. So if, for whatever reason, you need to downgrade your IPDirector software, YOU MUST reinstall the old AVH driver (provided with older IPDirector versions).

1.5 Use of Software player.

The IPDirector version 5.8 can be used to browse content (XT[2] content or files) from the software player. This software player takes CPU resources on the IP Director workstation to decode the images. Be careful when designing your setups to take this information into consideration and especially for standalone workstations because the IP Director shares CPU resources with other services (synchro DB, routing, SQL2005). These services when loaded can use a large amount of CPU resources.

1.5.1 Physical memory

The IPDirector version 5.8 needs 2 GB of RAM. A warning will be raised every time the IPDirector will be started if the workstation doesn't meet this requirement.


1.5.2 IP Director 1U workstation (Pentium mobile)

IP Director 1U workstations based on the Pentium mobile motherboard (MB 896) **cannot be used** with IP Director version 5.8 as it is not powerful enough. You can identify this by right clicking on 'MyComputer' and choosing Properties. The System properties will display Intel® Pentium® M as the processor type.

1.5.3 IPDirector 1U workstation (Core Duo processor)

IP Director 1U worstations based on the Core Duo processor (MB 899 T2300 CPU) :

can be used with the software player but we have noticed some CPU peaks around 90% when the workstation is used to decode HD images (i.e DNxHD 100 mpbs) and when the workstation is used in standalone mode (running as database server, connected to an XT server and with synchroDB management). In this scenario, the IP Director interface can be slow some times due to the CPU usage. We strongly advise not to use this kind of workstation in standalone mode when the software player must be used to decode HD images.



- Is not suitable for use when decoding DVCPRO HD @ 100 Mbps, the CPU reaches 100% and the whole application becomes very slow.

1.5.4 IPDirector 3U workstation (Tyan or INTEL)

We have **not encountered any problems with IP Director 3U workstations** based on the Tyan or Intel motherboard (Tyan Tomcat i915 or DG965 or DG33)

However a **3U workstation based on the Tyan motherboard cannot be used with the software player for HD browsing.**

1.5.5 IPDirector 3U workstation (i7 motherboard X8ST3-F)

This workstation is suitable for use with a software player whatever the codec.

1.6 Use of IP Drive

The IPDirector version 5.8 can be used to browse nearline footage including removable hard drives connected to a workstation (XFile, XStore, ...). When using IDE drives, be sure only one access to these drives are made at one time otherwise the bandwidth performances will be very poor (i.e recording and browsing on such drives at the same time, or browsing and restoring at the same time).

2 New functions

- 1. The documents
 - IPDirector V58 New Features.pdf,
 - IPDirector V58 E2A.pdf,
 - IPDirector V58 APIMOS.pdf

provided with this release note will give you a detailed overview of the new functions in IP Director version 5.8 compared to version 5.6.

2. Here is the list of the HTA provided with the version 5.8:

Name	What it does			
[IP]Director_5_Check_DB.hta	Checks the full text search configuration for the IP Director database. Checks the IPEngine licence installation on the database server.			
[IP]Director_5_ConfigGenerator.hta	Creates an XLS file with all the information related to the setup.			
[IP]Director_5_ImportExport.hta	Imports and exports target definition			
[IP]Director_5_Storage.hta	Deletes an offline nearline directory from the database			
[IP]Director_5_OrphanedLow2Bin.hta	Drops all clips including only lo-res clips into a bin.			
[IP]Director_5_Timeline2Bin.hta	Drops all clips used in a specific timeline into a bin			
[IP]Director_5_XML_Queues.hta	Display all XML files still pending in :Display all XML files still pending in : - xml units - IP Scheduler import directories - Export logs directories			

Refer to the document **Application_Note_[IP]Director_5.8_HTA.pdf** for more information on these HTAs.

3. The IPDirector version 5.8 is provided with new web interfaces dedicated to monitor your setup:

Refer to the web toolkit application note: Application_Note_Web_Toolkit_5.8.pdf



IP Director version 5.8 (v3)

Date: 09-sept-2010 Page: 5 File: IPDirector_release_note_V5.83.50.

doc

3 Bug fixes

On Ni 17955 assets 17962 Asset 13252 BEXEL 20222 Work 12776 RTS 18098 not pr 15313 RTL 13067 IMG 13435 RTBF	yout stopped, not possible to control XT channels. Nine Hi-lo setup, when creating clips, sometimes the hi-lo association is not done correctly. In fact, the system creates 2 sets, one with the hi and one with the lo-res. set coherence break but assetitems have the same TCs XEL Clip is removed from a bin if the Nearline file is deleted. orkstation channel as an option for db explorer, ip logger etc is greyed out	Sky News CHANNEL NINE BEXEL	AB Roll Playlist Asset Asset	05.76.20 05.74.20 05.74.20
17955 assets 17962 Asset 13252 BEXEL 20222 Work 12776 RTS 18098 not pr 15313 RTL 13067 IMG 13435 RTBF	sets, one with the hi and one with the lo-res. Set coherence break but assetitems have the same TCs XEL Clip is removed from a bin if the Nearline file is deleted. Orkstation channel as an option for db explorer, ip logger etc is greyed out		Asset	
17962 Asset 13252 BEXEI 20222 Work 12776 RTS 18098 not pr 15313 RTL 13067 IMG 13435 RTBF	set coherence break but assetitems have the same TCs XEL Clip is removed from a bin if the Nearline file is deleted. orkstation channel as an option for db explorer, ip logger etc is greyed out		Asset	
13252 BEXEL 20222 Work 12776 RTS 18098 not p 15313 RTL 13067 IMG 13435 RTBF	XEL Clip is removed from a bin if the Nearline file is deleted. orkstation channel as an option for db explorer, ip logger etc is greyed out	BEXEL		05 74 20
20222 Work 12776 RTS 18098 not pp 15313 RTL 13067 IMG 13435 RTBF	orkstation channel as an option for db explorer, ip logger etc is greyed out	BEXEL		03.7 7.20
12776 RTS 18098 not po 15313 RTL 13067 IMG 13435 RTBF			Bin Management	05.63.70
18098 not po 15313 RTL 13067 IMG 13435 RTBF		World Cup 2010	Channel Management	05.80.60
15313 RTL 13067 IMG 13435 RTBF	S Autoname clip not taken in account for a log drag and dropped in a bin	RTS	Clip Management	05.62.40
13067 IMG 13435 RTBF	t possible to mark in on a recorder		Clip Management	05.74.50
13435 RTBF	L Manual regrab thumbnail on control panel store the image locally and is not visible on the network	RTL	Control Panel	05.64.20
	G Clips created in IPD are not created even though it is successful	IMG	Control Panel	05.62.40
12506 Dowlet	BF Wrong lock status when the channel switch in IDLE state.	RTBF - NUMPROD	Control Panel	05.62.40
13590 ParkP	rkPost "Auto calculation of the timecode" rolls the timecode 2s after the end of a clip	ParkPost	Control Panel	05.63.70
20171 Upda	date button becomes unavailable when loading asset without XT clips	World Cup 2010	Control Panel	05.80.60
19101 NEP	P Use of control panel shortcut functions changed since IPD v5.64.50	NEP	Control Panel	05.64.50
17952 D&d a	d a playlist on the video display of the control panel does not work	Sky News	Control Panel	05.74.20
19407 Saved	ved Filter : Owner = mine is published as Owner = user	Sky News	Database Explorer	05.75.70
14280 we co	couldn't see the VARID of an offline file in the IPD	FOXTEL	Database Explorer	05.71.10
14330 CBS	S Database Explorer does not show individual clip elements of all assets	CBS	Database Explorer	05.63.50
14769 CBS	S Thumbnails view introduces multiple bugs in the Database explorer	CBS	Database Explorer	05.64.20
12598 F2 V	When associating clips XT as hi and lo, clip elements icons are wrong -> A manual refresh is needed	F2	Database Explorer	05.61.90
15755 RTL	L A Nearline file can't be restored in a specific bank, the interface allows it.	RTL	Database Explorer	05.64.20
17355 TVB	B Printing sheet in DB explorer overlaps status icons	TVB	Database Explorer	05.73.00
17959 Wher	nen associating asset items to asset with the associate asset item window, the asset item column is not updated.		Database Explorer	05.74.20
15114 COM		COMCAST		
12954 HBS	MCAST Database 5.16.40 is in recovery mode FULL	CONICAST	Database Service	05.64.20



IP Director version 5.8 (v3)

File: IPDirector_release_note_V5.83.50. doc Date: 09-sept-2010 Page: 6

13583 NEP Fill Key 0.5.63.70 19589 CS Sending a rigo levement of Fill Key 0.5.63.70 19580 CS Sending a rigo levement of Fill Key 0.5.80.00 20154 Sometimes, the filter "owner" doesn't give any result. 19580 Freeze on FCP Sending a rigo levement of Fill Key 0.5.80.00 19580 Freeze on FCP Sending a rigo levement of Fill Key 0.5.80.00 19590 Freeze on FCP Sending a rigo levement of Fill Key 0.5.80.00 19591 Freeze on FCP Sending a rigo levement of Fill Key 0.5.80.00 19591 Del Satency Sky News General 0.5.76.20 19592 Sky News General 0.5.60.00 19594 Del Satency Sky News General 0.5.60.00 19594 The Fill Key trouble if you minimize a Keyword grid and restore it (Only present on Tyan computer ?) RTL General 0.5.60.00 13819 RTBF Settings - Assigned PGM on GPI IN 8 is no saved in the Multicam RTBF - NUMPROD GPI 0.5.63.70 12740 RTBF Status of the streaming target in ingest Scheduler stays red after a failed job RTBF - NUMPROD GPI 0.5.63.70 12740 RTBF Status of the streaming target in ingest Scheduler stays red after a failed job RTBF - NUMPROD Ingest Scheduler 0.5.74.20 137974 NBC Edit Ingest Scheduler Blocks yield wrong block in Edit Dialog NBC Ingest Scheduler 0.5.74.20 13970 Ingesting block desposering from the legest Scheduler 0.5.75.70 13910 Ingesting block desposering from the legest Scheduler 0.5.75.70 13910 Ingesting block desposering from the legest Scheduler 0.5.80.60 13910 Ingesting block desposering from the legest Scheduler 0.5.80.60 13910 Ingesting block desposering from the legest Scheduler 0.5.80.60 13910 Ingesting block desposering from the legest Scheduler 0.5.80.60 13910 Ingesting block desposering from the legest Scheduler 0.5.80.60 13910 Ingesting block desposering from the legest Scheduler 0.5.80.60 13910 Ingesting block desposering from the legest Scheduler 0.5.80.60 13910 Ingesting block desposering from the legest Scheduler 0.5.80.60 13910 Ingesting block desposer					
20154 Sometimes, the filter "owner" doesn't give any result. 2015989 Freeze on FCP 20157 Sky News 20157 General 20157 C.D 201587 Background selection replaced by the default one after upgrading the version 20169 RTL Display trouble if you minimize a Keyword grid and restore it (Only present on Tyan computer ?) 20169 RTL Display trouble if you minimize a Keyword grid and restore it (Only present on Tyan computer ?) 20169 RTL Display trouble if you minimize a Keyword grid and restore it (Only present on Tyan computer ?) 20169 RTBF Settings - Assigned PGM on GPI NB is no saved in the Multicam 20169 RTBF Settings - Assigned PGM on GPI NB is no saved in the Multicam 20169 RTBF Status of the streaming target in Ingest Scheduler stays red after a failed job 20169 RTBF - NUMPROD 20179 RTBF Status of the streaming target in Ingest Scheduler stays red after a failed job 20179 RTBF Status of the streaming target in Ingest Scheduler stays red after a failed job 20179 RTBF - NUMPROD 20187 NBC Edit Ingest Scheduler stays red after a failed job 20179 NBC Edit Ingest Scheduler 20179 NBC Edit Ingest Scheduler Blocks yield wrong block in Edit Dialog 20187 One one track, not possible to select all the associated channels by SHIFT+click 20187 One one track, not possible to select all the associated channels by SHIFT+click 20189 NBC Ingest Scheduler 20189 NBC Ingest	13263	NEP Fill/Key clips do not both re-cue when TC In are different.	NEP	Fill & Key	05.63.70
1998 Freeze on FCP Sky News General 05.76.20	19589	CBS Sending a clip element of a Fill&Key association returns an faulty error message 'clip already in the queue'	CBS	Fill & Key	05.80.20
Background selection replaced by the default one after upgrading the version World Cup 2010 General O5.80.80 19994 D8 latency ORTL Display trouble if you minimize a Keyword grid and restore it (Only present on Tyan computer?) RTL General O5.64.20 RTL Siplay trouble if you minimize a Keyword grid and restore it (Only present on Tyan computer?) RTL General O5.64.20 RTB Status of the streaming target in lingest Scheduler with Multicam RTB - NUMPROD Ingest Scheduler O5.62.40 Ingest Scheduler O5.74.20 Ingest Scheduler O5.74.20 Ingest Scheduler O5.74.20 Ingest Scheduler O5.74.20 Ingest Scheduler O5.74.10 Ingest Scheduler O5.75.70 One one Track, not possible to select all the associated channels by SHIFT-click World Cup 2010 Ingest Scheduler O5.75.70 One one track, not possible to select all the associated channels by SHIFT-click World Cup 2010 Ingest Scheduler O5.80.60 20612 we are seeing Asset Coherence breaks on one of our machine in PCR. World Cup 2010 Ingest Scheduler O5.81.30 20877 When pluggin 1p drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive O5.82.20 19294 Sky 1-tlob audio spike on replace function in IPEdit and Multicam Sky News Ip Edit O5.75.30 Ingest Scheduler O5.74.20 Ingest Scheduler O5.74.20 Ingest Scheduler O5.75.30 Ingest Scheduler O5.75.30 Ingest Scheduler O5.75.30 Ingest Scheduler O5.75.30 Ingest Scheduler O5.76.20 Ingest Scheduler	20154	Sometimes, the filter "owner" doesn't give any result.	World Cup 2010	Filters	05.80.60
19994 DB latency 20069 RTL Display trouble if you minimize a Keyword grid and restore it (Only present on Tyan computer?) RTL General 05.64.20 13819 RTBF Settings - Assigned PGM on GPI IN 8 is no saved in the Multicam RTBF - NUMPROD GPI 05.63.70 12740 RTBF Status of the streaming target in Ingest Scheduler stays red after a failed job RTBF - NUMPROD Ingest Scheduler 05.62.40 17961 varID is not available in the settings of the ingest blocs Ingest Scheduler 05.74.20 17974 NBC Edit Ingest Scheduler Display to the ingest Scheduler 05.74.20 18930 Ingesting block desapearing from the Ingest Scheduler 05.74.10 19300 Ingesting block desapearing from the Ingest Scheduler 05.75.70 20187 One one track, not possible to select all the associated channels by SHIFT+click World Cup 2010 Ingest Scheduler 05.80.60 20612 we are seeing Asset Coherence breaks on one of our machine in PCR. World Cup 2010 Ingest Scheduler 05.80.60 20634 Archived clips do not check into IPDrive/Nearline World Cup 2010 IP Drive 05.81.30 20877 Wifen pluggin ip drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive 05.82.20 18959 Wite is deactivated when switching timeline to player in trim mode Ip Edit 05.74.20 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit 05.74.20 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit 05.74.20 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit 05.74.20 18064 Cus metadata profile when converting a playlist to a timeline NBC Ip Edit 05.74.20 18079 Ip Edit 05.74.50 181791 Timeline : copy short/copy long NBC Ip Edit 05.74.50 181810 Effect and Overwrite Node I can't make an operation after a add effect Ip Edit 05.74.50 181810 Lose profile metadata Ip Edit 05.74.50 181810 Lose profile metadata Ip Edit 05.74.50 18079 Lose profile metadata Ip Edit 05.74.50 18075 Lose profile metadata Ip Edit 05.74.50 18075 Lose pro	19989	Freeze on FCP	Sky News	General	05.76.20
20069 RTL Display trouble if you minimize a Keyword grid and restore it (Only present on Tyan computer?) RTL General 05.64.20 13819 RTBF Settings - Assigned PGM on GPI IN 8 is no saved in the Multicam RTBF - NUMPROD GPI 05.63.70 12740 RTBF Status of the streaming target in Ingest Scheduler stays red after a failed job Ingest Scheduler 05.62.40 17961 vari Di snot available in the settings of the ingest blocs Ingest Scheduler 05.74.20 17974 NBC Edit Ingest Scheduler Blocks yield wrong block in Edit Dialog NBC Ingest Scheduler 05.74.10 19300 Ingesting block desapearing from the Ingest Scheduler 05.74.10 19300 Ingesting block desapearing from the Ingest Scheduler 05.75.70 20187 One one track, not possible to select all the associated channels by SHIFT+click World Cup 2010 Ingest Scheduler 05.80.60 20612 we are seeing Asset Coherence breaks on one of our machine in PCR. World Cup 2010 Ingest Scheduler 05.81.30 20694 Archived clips do not check into IPDrive/Nearline World Cup 2010 Ingest Scheduler 05.81.30 20877 WHen pluggin lp drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive 05.82.20 19294 Sky +1db audio spike on replace function in IPEdit and Multicam Sky News Ip Edit 05.64.60 18569 Mute is deactivated when switching timeline to player in trim mode Ip Edit 05.74.20 18018 Lexperienced an audio Issue when copying an EDL from IP Edit to an XT server. Ip Edit 05.74.20 18018 Lexperienced an audio Issue when copying an EDL from IP Edit to an XT server. Ip Edit 05.74.20 17916 Timeline : copy short/copy long NBC Ip Edit 05.74.20 17917 IPEdit cannot load timeline NBC Ip Edit 05.74.50 17918 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 17918 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 18075 Copy TL, lose profile metadata NBC Ip Edit 05.74.50 18075 Copy TL, lose profile metadata NBC Ip Edit 05.74.50 Ip Edit 05.74.50 In Edit 05.74.50 In Edit 05.74.50 In Edit 05.74.50	20387	Background selection replaced by the default one after upgrading the version	World Cup 2010	General	05.80.80
13819 RTBF Settings - Assigned PGM on GPI IN 8 is no saved in the Multicam RTBF - NUMPROD GPI 05.63.70 12740 RTBF Status of the streaming target in legest Scheduler stays red after a failed job RTBF - NUMPROD Ingest Scheduler 05.62.40 12791 varID is not available in the settings of the ingest blocs Ingest Scheduler 05.74.20 13910 NBC Edit ingest Scheduler Blocks yield wrong block in Edit Dialog NBC Ingest Scheduler 05.74.10 19300 Ingesting block desapearing from the Ingest Scheduler Sky News Ingest Scheduler 05.75.70 20187 One one track, not possible to select all the associated channels by SHIFT+click World Cup 2010 Ingest Scheduler 05.80.60 20612 we are seeing Asset Coherence breaks on one of our machine in PCR. World Cup 2010 Ingest Scheduler 05.81.30 20694 Archived clips do not check into IPDrive/Nearline World Cup 2010 Ingest Scheduler 05.81.30 20877 WHen pluggin Ip drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive 05.81.30 18599 Mute is deactivated when switching timeline to player in trim mode Ip Edit 05.75.30 187983 D, F,G keys do not clear marks in player window. (clicking doos) 18018 I experienced an audio issue when copyring an EDL from IP Edit to an XT server. Ip Edit 05.74.20 18916 I Desert and audio issue when copyring an EDL from IP Edit to an XT server. Ip Edit 05.74.20 18916 I Timeline : copy short/copy long NBC Ip Edit 05.74.50 17917 IPEdit cannot load timeline In Copyring an EDL from IP Edit to an XT server. Ip Edit 05.74.50 18917 I PEdit cannot load timeline In Copyring an EDL from IP Edit to an XT server. Ip Edit 05.74.50 18918 I Desert work in the preview panel In Edit on S.74.50 18918 Custon Merchand Custon In Copyring ADL from IP Edit to an XT server. Ip Edit 05.74.50 18919 Edit 05.74.50 18910 Edit 05.74.50	19994	DB latency	Sky News	General	05.76.20
12740 RTBF Status of the streaming target in Ingest Scheduler stays red after a failed job 17961 var10 is not available in the settings of the ingest blocs 17974 NBC Edit Ingest Scheduler 05.74.20 17974 NBC Edit Ingest Scheduler 05.74.10 17974 NBC Edit Ingest Scheduler 05.74.10 17974 NBC Edit Ingest Scheduler 05.74.10 17975 NBC Edit Ingest Scheduler 05.74.10 17976 NBC Edit Ingest Scheduler 05.74.10 17976 NBC Edit Ingest Scheduler 05.74.10 17976 NBC Edit Ingest Scheduler 05.75.70 17977 NBC Edit Ingest Scheduler 05.75.70 17978 NBC Edit Ingest Scheduler 05.75.70 17978 NBC Edit Ingest Scheduler 05.80.60 17978 NBC Edit Ingest Scheduler 05.74.20 17979 Ingest Scheduler 05.74.20 17979 Ingest Scheduler 05.74.50 17979 Ingest Scheduler	20069	RTL Display trouble if you minimize a Keyword grid and restore it (Only present on Tyan computer ?)	RTL	General	05.64.20
17961 varID is not available in the settings of the ingest blocs 17974 NBC Edit Ingest Scheduler Blocks yield wrong block in Edit Dialog 189300 Ingesting block desapearing from the Ingest Scheduler 19300 Ingesting block desapearing from the Ingest Scheduler 20187 One one track, not possible to select all the associated channels by SHIFT+click 20187 One one track, not possible to select all the associated channels by SHIFT+click 20187 World Cup 2010 Ingest Scheduler 205.80.60 20612 we are seeing Asset Coherence breaks on one of our machine in PCR. 20624 World Cup 2010 Ingest Scheduler 205.81.30 20694 Archived clips do not check into IPDrive/Nearline 20877 WHen pluggin ip drive, the DB processor remains at 100% for a few minutes 20878 World Cup 2010 IP Drive 205.81.30 20878 Sky *1 dib audio spike on replace function in IPEdit and Multicam 20879 Mute is deactivated when switching timeline to player in trim mode 20870 With its deactivated when switching timeline to player in trim mode 305.64.60 305.64	13819	RTBF Settings - Assigned PGM on GPI IN 8 is no saved in the Multicam	RTBF - NUMPROD	GPI	05.63.70
17974 NBC Edit Ingest Scheduler Blocks yield wrong block in Edit Dialog NBC Ingest Scheduler 05.74.10 19300 Ingesting block desapearing from the Ingest Scheduler 05.75.70 20187 One one track, not possible to select all the associated channels by SHIFT+click World Cup 2010 Ingest Scheduler 05.80.60 20612 we are seeing Asset Coherence breaks on one of our machine in PCR. World Cup 2010 Ingest Scheduler 05.81.30 20694 Archived clips do not check into IPDrive/Nearline World Cup 2010 Ingest Scheduler 05.81.30 20877 Withen pluggin Ip drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive 05.81.30 20877 Withen pluggin Ip drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive 05.82.20 20877 Withen pluggin Ip drive, the DB processor remains at 100% for a few minutes Sky News Ip Edit 05.64.60 20877 Withen pluggin Ip drive, the DB processor remains at 100% for a few minutes Sky News Ip Edit 05.64.60 20878 World Cup 2010 IP Drive 05.82.20 20879 World Cup 2010 IP Drive 05.82.20 20879 World Cup 2010 IP Drive 05.82.20 20870 World Cup 2010 IP Drive 05.82.20 20870 World Cup 2010 IP Drive 05.82.20 20870 World Cup 2010 IP Drive 05.82.20 20871 World Cup 2010 IP Drive 05.82.20 20871 World Cup 2010 IP Drive 05.82.20 20871 World Cup 2010 IP Drive 05.82.20 20872 World Cup 2010 IP Drive 05.82.20 20872 World Cup 2010 IP Drive 05.82.20 20873 World Cup 2010 IP Drive 05.82.20 20874 World Cup 2010 IP Drive 05.82.20 20875 World Cup 2010 IP Drive 05.82.20 20875 World Cup 2010 IP Drive 05.82.20 20876 World Cup 2010 IP Drive 05.82.20 20877 World Cup 2010 IP Drive 05.82	12740	RTBF Status of the streaming target in Ingest Scheduler stays red after a failed job	RTBF - NUMPROD	Ingest Scheduler	05.62.40
Ingest ing block desapearing from the Ingest Scheduler One one track, not possible to select all the associated channels by SHIFT+click World Cup 2010 Ingest Scheduler O5.80.60 20612 we are seeing Asset Coherence breaks on one of our machine in PCR. World Cup 2010 Ingest Scheduler O5.81.30 20694 Archived clips do not check into IPDrive/Nearline World Cup 2010 IP Drive O5.81.30 20877 When pluggin Ip drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive O5.82.20 19294 Sky +1db audio spike on replace function in IPEdit and Multicam Sky News Ip Edit O5.74.60 18569 Mute is deactivated when switching timeline to player in trim mode Ip Edit O5.75.30 17983 D,F,G keys do not clear marks in player window (clicking does) Ie experienced an audio issue when copying an EDL from IP Edit to an XT server. Ip Edit O5.74.20 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit O5.74.50 17916 Timeline: copy short/copy long NBC Ip Edit O5.74.50 17917 IPEdit cannot load timeline NBC Ip Edit O5.74.50 18170 IPPOWINGS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit O5.74.50 18170 IB Edit O5.74.50 18171 Effect and Overwrite Mode I can't make an operation after a add effect NBC Ip Edit O5.74.50 O5.74.50 O7.74.50 O7.74	17961	varID is not available in the settings of the ingest blocs		Ingest Scheduler	05.74.20
20187 One one track, not possible to select all the associated channels by SHIFT+click World Cup 2010 Ingest Scheduler 05.80.60 20612 we are seeing Asset Coherence breaks on one of our machine in PCR. World Cup 2010 Ingest Scheduler 05.81.30 20694 Archived clips do not check into IPDrive/Nearline World Cup 2010 IP Drive 05.81.30 20877 WHen pluggin Ip drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive 05.82.20 20877 WHen pluggin Ip drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive 05.82.20 20878 Sky +1db audio spike on replace function in IPEdit and Multicam Sky News Ip Edit 05.64.60 20879 Mute is deactivated when switching timeline to player in trim mode Ip Edit 05.74.20 20879 Ip Edit	17974	NBC Edit Ingest Scheduler Blocks yield wrong block in Edit Dialog	NBC	Ingest Scheduler	05.74.10
we are seeing Asset Coherence breaks on one of our machine in PCR. World Cup 2010 Ingest Scheduler O5.81.30 20694 Archived clips do not check into IPDrive/Nearline World Cup 2010 IP Drive O5.81.30 20877 When pluggin lp drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive O5.82.20 Sky +1db audio spike on replace function in IPEdit and Multicam Sky News Ip Edit O5.575.30 17983 D,F,G keys do not clear marks in player window (clicking does) I experienced an audio issue when copying an EDL from IP Edit to an XT server. Ip Edit O5.74.20 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit O5.74.20 17916 Timeline: copy short/copy long NBC Ip Edit O5.74.50 17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDIt with bad EDL content NBC Ip Edit O5.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect Ip Edit O5.74.50	19300	Ingesting block desapearing from the Ingest Scheduler	Sky News	Ingest Scheduler	05.75.70
Archived clips do not check into IPDrive/Nearline World Cup 2010 IP Drive 05.81.30 20877 WHen pluggin Ip drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive 05.82.20 19294 Sky +1db audio spike on replace function in IPEdit and Multicam Sky News Ip Edit 05.64.60 18569 Mute is deactivated when switching timeline to player in trim mode Ip Edit 05.75.30 17983 D,F,G keys do not clear marks in player window (clicking does) Ip Edit 05.74.20 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit 05.74.20 17916 Timeline: copy short/copy long NBC Ip Edit 05.74.50 17917 IPEdit cannot load timeline NBC Ip Edit 05.74.50 17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect Ip Edit 05.74.50 18171 Or Oout Doesn't work in the preview panel RBC Ip Edit 05.74.50 Or Oout Doesn't work in the preview panel In Edit Or Or Out Doesn't work in the preview panel RBC Ip Edit Or Or Out Doesn't work in the preview panel In Edit Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel In Edit Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Out Doesn't work in the preview panel Or Or Or Or Drevented Called the panel of the	20187	One one track, not possible to select all the associated channels by SHIFT+click	World Cup 2010	Ingest Scheduler	05.80.60
WHen pluggin Ip drive, the DB processor remains at 100% for a few minutes World Cup 2010 IP Drive 05.82.20 19294 Sky +1db audio spike on replace function in IPEdit and Multicam Sky News Ip Edit 05.64.60 18569 Mute is deactivated when switching timeline to player in trim mode Ip Edit 05.75.30 17983 D,F,G keys do not clear marks in player window (clicking does) Ip Edit 05.74.20 18018 I experienced an audio issue when copying an EDL from IP Edit to an XT server. Ip Edit 05.74.20 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit 05.74.50 17916 Timeline: copy short/copy long NBC Ip Edit 05.74.50 17917 IPEdit cannot load timeline NBC Ip Edit 05.74.50 17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect Ip Edit 05.74.50 18172 Go To Out Doesn't work in the preview panel Ip Edit 05.74.50 NBC Ip Edit 05.74.50 18195 Copy TL, lose profile metadata NBC Ip Edit 05.74.50	20612	we are seeing Asset Coherence breaks on one of our machine in PCR.	World Cup 2010	Ingest Scheduler	05.81.30
19294 Sky +1db audio spike on replace function in IPEdit and Multicam Sky News Ip Edit 05.64.60 18569 Mute is deactivated when switching timeline to player in trim mode Ip Edit 05.75.30 17983 D,F,G keys do not clear marks in player window (clicking does) Ip Edit 05.74.20 18018 I experienced an audio issue when copying an EDL from IP Edit to an XT server. Ip Edit 05.74.20 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit 05.74.20 17916 Timeline: copy short/copy long NBC Ip Edit 05.74.50 17917 IPEdit cannot load timeline NBC Ip Edit 05.74.50 17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect Ip Edit 05.74.52 18075 Copy TL, lose profile metadata On the preview panel Ip Edit 05.74.20 18095 during a copy clips locally, some clips went offline create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	20694	Archived clips do not check into IPDrive/Nearline	World Cup 2010	IP Drive	05.81.30
Mute is deactivated when switching timeline to player in trim mode 17983 D,F,G keys do not clear marks in player window (clicking does) 18018 I experienced an audio issue when copying an EDL from IP Edit to an XT server. 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit 05.74.20 17916 Timeline: copy short/copy long NBC Ip Edit 05.74.50 17917 IPEdit cannot load timeline NBC Ip Edit 05.74.50 17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect IB Edit 05.74.50 18172 Go To Out Doesn't work in the preview panel Ip Edit 05.74.50 NBC Ip Edit 05.74.50 18175 Copy TL, lose profile metadata NBC Ip Edit 05.74.50 Ip Edit 05.74.50 OS.74.50 Ip Edit 05.74.50	20877	WHen pluggin Ip drive, the DB processor remains at 100% for a few minutes	World Cup 2010	IP Drive	05.82.20
17983 D,F,G keys do not clear marks in player window (clicking does) 18018 I experienced an audio issue when copying an EDL from IP Edit to an XT server. 18064 Lose metadata profile when converting a playlist to a timeline 18064 I p Edit 18065 D, F,G keys do not clear marks in player window (clicking does) 18066 I p Edit 18067 D, F,G keys do not clear marks in player window (clicking does) 18068 D, F,G keys do not clear marks in player window (clicking does) 18068 D, F,G keys do not clear marks in player window (clicking does) 18068 D, F,G keys do not clear marks in player window (clicking does) 18068 D, F,G keys do not clear marks in player window (clicking does) 18064 D, F,G keys do not clear marks in player window (clicking does) 18064 D, F,G keys do not clear marks in player window (clicking does) 18064 D, F,G keys do not clear marks in player window (clicking does) 18064 D, Edit D, F,G keys do not clear marks in player window (clicking does) 1807 Lose profile when converting a DL from IP Edit to a N. V.	19294	Sky +1db audio spike on replace function in IPEdit and Multicam	Sky News	lp Edit	05.64.60
18018 I experienced an audio issue when copying an EDL from IP Edit to an XT server. 18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit 05.74.20 17916 Timeline: copy short/copy long NBC Ip Edit 05.74.50 17917 IPEdit cannot load timeline NBC Ip Edit 05.74.50 17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect Ip Edit 05.74.50 18172 Go To Out Doesn't work in the preview panel Ip Edit 05.74.50 18095 Copy TL, lose profile metadata NBC Ip Edit 05.74.50 Ip Edit 05.74.50 Copy TL, lose profile metadata NBC Ip Edit 05.74.50 Ip Edit 05.74.50 Create Clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	18569	Mute is deactivated when switching timeline to player in trim mode		Ip Edit	05.75.30
18064 Lose metadata profile when converting a playlist to a timeline NBC Ip Edit O5.74.20 17916 Timeline: copy short/copy long NBC Ip Edit O5.74.50 17917 IPEdit cannot load timeline NBC Ip Edit O5.74.50 17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit O5.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect Ip Edit O5.75.10 18172 Go To Out Doesn't work in the preview panel Ip Edit O5.74.50 18075 Copy TL, lose profile metadata NBC Ip Edit O5.74.50 18095 during a copy clips locally, some clips went offline create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	17983	D,F,G keys do not clear marks in player window (clicking does)		lp Edit	05.74.20
17916 Timeline: copy short/copy long NBC Ip Edit 05.74.50 17917 IPEdit cannot load timeline NBC Ip Edit 05.74.50 17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect Ip Edit 05.75.10 18172 Go To Out Doesn't work in the preview panel Ip Edit 05.74.52 18075 Copy TL, lose profile metadata NBC Ip Edit 05.74.20 18095 during a copy clips locally, some clips went offline Ip Edit 05.74.50 create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	18018	I experienced an audio issue when copying an EDL from IP Edit to an XT server.		lp Edit	05.74.20
17917 IPEdit cannot load timeline NBC Ip Edit 05.74.50 17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect Ip Edit 05.75.10 18172 Go To Out Doesn't work in the preview panel Ip Edit 05.74.52 18075 Copy TL, lose profile metadata NBC Ip Edit 05.74.20 Ip Edit 05.74.50	18064	Lose metadata profile when converting a playlist to a timeline	NBC	lp Edit	05.74.20
17948 CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content NBC Ip Edit 05.74.50 18170 Effect and Overwrite Mode I can't make an operation after a add effect Ip Edit 05.75.10 18172 Go To Out Doesn't work in the preview panel Ip Edit 05.74.52 18075 Copy TL, lose profile metadata NBC Ip Edit 05.74.20 18095 during a copy clips locally, some clips went offline create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	17916	Timeline : copy short/copy long	NBC	Ip Edit	05.74.50
18170 Effect and Overwrite Mode I can't make an operation after a add effect 18172 Go To Out Doesn't work in the preview panel 18075 Copy TL, lose profile metadata NBC Ip Edit 05.74.20 18095 during a copy clips locally, some clips went offline create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	17917	IPEdit cannot load timeline	NBC	lp Edit	05.74.50
18172 Go To Out Doesn't work in the preview panel Ip Edit 05.74.52 18075 Copy TL, lose profile metadata NBC Ip Edit 05.74.20 18095 during a copy clips locally, some clips went offline Ip Edit 05.74.50 create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	17948	CUSTOMER - NBC - OLYMPICS - Flatten video slip from IPEDit with bad EDL content	NBC	Ip Edit	05.74.50
18075 Copy TL, lose profile metadata NBC Ip Edit 05.74.20 18095 during a copy clips locally, some clips went offline create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	18170	Effect and Overwrite Mode I can't make an operation after a add effect		Ip Edit	05.75.10
18095 during a copy clips locally, some clips went offline Create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	18172	Go To Out Doesn't work in the preview panel		Ip Edit	05.74.52
create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is	18075	Copy TL, lose profile metadata	NBC	Ip Edit	05.74.20
	18095	during a copy clips locally, some clips went offline		Ip Edit	05.74.50
18096 27/12/2071 Ip Edit 05.74.50		create clip from timeline seems to sometimes produce a clip that is flagged in multicam as 1080i PAL and creation date is			
	18096	27/12/2071		Ip Edit	05.74.50

Email :support@evs.tv Tel: +32 4 361 7000 Fax: +32 4 361 7099 IP Director



IP Director version 5.8 (v3)

File: IPDirector_release_note_V5.83.50. doc Date: 09-sept-2010 Page: 7

18219	CUSTOMER - OLYMPICS - The editors have been complaining recently that audio dissolves are not being rendered properly	NBC	lp Edit	05.74.10
18456	Focus Player Mark IN" and "Go to IN" in player window does not work intermittently		Ip Edit	05.74.52
12765	Now Line did not change color when an IN marked on the now position		Ip Edit	05.61.20
12738	NBC Removing 8 frames from the end of a block produced (10 frame error)	NBC	Ip Edit	05.62.40
14005	IP Edit Timeline clips play at wrong speed		Ip Edit	05.62.40
13318	HBS Logsheet export doesn't create the XML file	HBS	lpLogger	05.63.70
15075	Invalid null character is generated in logsheet export when RR has no camera	Sky sports	lpLogger	05.71.80
13068	ESPN TC USER not present in CSV export	ESPN	lpLogger	05.62.40
20542	Association with PM lost in some LS	World Cup 2010	lpLogger	05.81.10
20545	Cannot import an XML file when the taguserfields is empty	World Cup 2010	IpLogger	05.81.10
17547	OBS Vancouver Play-list import via XML creates 2 identical play-list	OBS	IpScheduler Service	05.73.30
12671	Naming of the tabs not reflected in Select Filter Condition window(Keywords)		Keyword Grid	05.62.20
	WC2010 Identical keywords with different cases (upper/lower) are imported as different keywords and induce side effects in			
20317	kwd grid / dictionnary	World Cup 2010	Keyword List	05.80.60
13759	RTBF Ingest scheduler window not saved in a non-admin user layout	RTBF - NUMPROD	Layout Management	05.63.70
19299	UF and UF values duplicated when importing XML metadata generated by Xedio	Sky News	Metadata	05.75.60
20096	Skynews problem run order 2100 [urgent]	Sky News	MOS	05.75.62
13055	Tier2 !PSU1 !PSU2 error message not present in the IPDP OSD		Multicam	05.62.40
13103	CAROLINA HURRICANES Restoring file from nearline always takes the first element in the asset.	CAROLINA HURRICANES	Nearline	05.63.50
15360	VCF filename.mov files coming from XSan withfilename.mov companion file crashes timecode extractor	VCF	Nearline	05.64.20
18226	Rescan of a sub folder, rescanall the folders of the nearline		Nearline	05.75.10
20075	SKY: a lot of XML import unsuccessful on the nearline	Sky News	Nearline	05.76.10
20541	Cannot insert elements in a PL anymore	World Cup 2010	PlayList Management	05.81.10
18499	RTBF IP-Scheduler checks the Production Playlist code to import Third Party Playlits	RTBF - NUMPROD	PlayList Management	05.64.20
18224	Copy/move PLTL window shows the name with extra space characters at the end		PlayList Management	05.75.10
18225	Different behaviour with the FF button		PlayList Management	05.75.10
12760	Not possible to define a VideoEffect duration between 20 and 29 frame in the VideoEffect playlist panel		Playlist panel	05.62.40
18805	Channel One Cannot retrieve a playlist with cyrillic name in Playlist Panel	CHANNEL ONE	Playlist panel	05.75.20
20386	Bug Remote Installer - It displays RS422 AVH in the summary when AVH is not present	World Cup 2010	Remote Installer	05.80.80
	Auto-association set to TRUE on some workstations whereas others are set to FALSE	World Cup 2010	Remote Installer	05.81.10

Email :support@evs.tv Tel: +32 4 361 7000 Fax: +32 4 361 7099 IP Director





IP Director version 5.8 (v3)

Date: 09-sept-2010 Page: 8 File: IPDirector_release_note_V5.83.50.

doc

20705	Tier3 IP-API services autostarts (start all programs) on an IP-API Proxy workstation even if the autostart option is not checked	Wimbledon	Remote Installer	05.81.30
20692	Tier3 An IP-API workstation freshly installed in member of the group 'not installed' instead of 'global'	Wimbledon	Remote Installer	05.81.30
13100	CBS IPD Monitoring services do not work when local user is in a domain	CBS	Remote Installer	05.63.50
13032	XGames Config Generator.hta doesnt' work properly	XGames	Remote Installer	05.63.40
17964	Can't get rid of the "prefix" defined for XML files sent to XML units		Remote Installer	05.74.20
13767	18 char Workgroup name is too long		Routing Service	05.64.00
20333	Serial link connection lost	World Cup 2010	Routing Service	05.80.70
12773	Ip logger some shortcuts are missing from the list		Shortcuts	05.62.50
18217	Can create clips with Shuttle Pro remote even the maximum number of clips is reached.		Shuttle Pro	05.74.10
20229	Cannot toggle between Record channels with the HBSLOGGER users	World Cup 2010	Shuttle Pro	05.80.60
19464	Info lost in CTRL Panel when creating a new playlist	Sky News	Software player	05.75.90
19733	Certain clips in the "gang" systematically cue up the LoRes Clip on the XL, not the Lores file as expected	World Cup 2010	Software player	05.80.30
18067	In DNxHD, the aspect ratio is not correct in the software player.		Software player	05.74.20
13027	XGames Software player dumps several times	XGames	Software player	05.63.40
13301	Showtime XT disappears when using synchro in network mode	Showtime	SynchroDB Service	05.63.80
19747	RTBF Clip restored and present on XT but absent from the DB explorer	RTBF - NUMPROD	SynchroDB Service	05.64.20
19991	loss of synchronization on EF	Sky News	SynchroDB Service	05.76.20
13051	XGames When transferring a file to a destination , shouldn't we have a "file" icon in the "type" column	XGames	Transfer Monitoring	05.63.40
18228	Transfer Monitoring sometimes will not display the varID of the Job Type 10 (EDL+Flatten) jobs		Transfer Monitoring	05.75.10
18066	Processing device is wrong in the tfr monitoring window		Transfer Monitoring	05.74.20
20502	Still mode set to stop on last frame wait then jump when inserting clips in a PL	World Cup 2010	User's Rights	05.81.00
20546	Flatten PL to file transitions flattened as cuts and not dissolves	World Cup 2010	Xml Interop	05.81.10
20152	Files have wrong name when using the follwoing file name convention MXX%CAMLBL	World Cup 2010	Xml Interop	05.80.60
17956	Channel 9: When sending a flattening request, all the logs are added to the metadata for all the elements	CHANNEL NINE	Xml Interop	05.74.20
18069	Send to target send to an XT on another XT the lsmID of the destination is not correct in the tfr monitoring window.		Xml Interop	05.74.20
12764	XML file returned by IP doesn't match the convention name if the extension file is in capital letters		Xml Interop	05.62.40
13661	EVS UK Grabbing Image creates empty filenames (1).jpg		Xml Interop	05.63.70
13662	EVS UK Grabbing Image on a lores software player captures the a lores image		Xml Interop	05.63.70
13677	BYBTRC XML Metadata of a stream is not sent to FCP	BYBTRC	Xml Interop	05.63.70





IP Director version 5.8 (v3)

Date: 09-sept-2010 Page: 9 File: IPDirector_release_note_V5.83.50.

doc

From version 5.82.60 To version 5.82.90

i rom versio	11 3.02.00 TO VEISION 3.02.30			
Defect ID	Summary	Project	Module	Detected in Version
21401	No automatic cue on channel A or B	Sky News	AB Roll Playlist	05.82.70
21409	Next element don't cue after the play	Sky News	AB Roll Playlist	05.82.70
21424	AB Roll First element D&D in PL not cued	Sky News	AB Roll Playlist	05.82.70
21427	Insert Wrong Ripple and Cue after an insert of a multiselection	Sky News	AB Roll Playlist	05.82.70
21435	AB Roll Channel set to IDLE	Sky News	AB Roll Playlist	05.82.70
21477	AB Roll Next available element not Cued	Sky News	AB Roll Playlist	05.82.70
21557	AB Roll Clip not correctly Cued	Sky News	AB Roll Playlist	05.82.80
21536	US Open PM cannot be copied by GbE from the DBExplorer	ESPN	Database Explorer	05.82.70
21455	AB Roll user's manual not in the package		General	05.82.50
21492	BeTV Wrong Streaming status in the Ingest Scheduler - XML Unit management should be optimized	BE TV	Ingest Scheduler	05.82.60
	Flatten To XT Dump Xt Access Problem if i delete a clip while the flatten to XT, i have a			
17784	bad error message		Ip Edit	05.74.20
21509	Return 3rd party xml contain UMID of Lo Res clip	Delta Tre	IpScheduler Service	05.82.80
21400	bad duration in playlist panel after append clip	Sky News	Playlist panel	05.82.70
21456	Software player Does not correctly decode H264 files with TC less than a minute		Software player	05.82.50
21503	BBC Impossible to manage an XT, management failed at start up	BBC	SynchroDB Service	05.82.50



IP Director version 5.8 (v3)

Date: 09-sept-2010 Page: 10 File: IPDirector_release_note_V5.83.50.

21330	Bins non admin user can not modify a directory	User's Rights	05.82.70
		Delta Tre,	
21382	PlazaMedia Return 3rd party XML doesn't contain the UMD ID Clip in IPD 5.8	PlazaMedia Xml Interop	05.82.60
21508	H264 does not load correctly if an xml companion file exists	Xml Interop	05.82.80

From version 5.82.90 to 5.83.50

				Detected in
Defect ID	Summary	Project	Module	Version
	InsertClipInPlaylist and InsertVirtualElementInPlaylist doesn't take the default still			
22167	and start mode defined in the settings	RTBF - NUMPROD	API	05.83.20
21957	Foxtel It is impossible to subclip a clip on a server launched without recorder	FOXTEL	Clip Management	05.82.70
21687	Goto In/out does not work correctly when switching focus	NBC - Access Hollywood	Ip Edit	05.82.90
21689	E2A TL longer than 1H are not usable	NBC - Access Hollywood	Ip Edit	05.82.90
21512	Protect selected logs Not possible to protect more than 2 consecutive logs	BBC	IpLogger	05.82.40
	US Open Protect Media on a single relevant recorder create a ganged group with			
21538	one member.	ESPN	IpLogger	05.82.70
	Skynews Impossible to trace a UNSUCCESSFUL nearline import status in the IPD			
21861	logs	Sky News	Nearline	05.82.90
22165	Playlist element boundaries are not modified when clip is trimmed.	RTBF - NUMPROD	PlayList Management	05.83.20
21854	Foxtel Tags disappearing from the Playlist Panel	FOXTEL	Playlist panel	05.82.70



IP Director version 5.8 (v3)

Date: 09-sept-2010 Page: 11 File: IPDirector_release_note_V5.83.50.

doc

4 Known bugs

Defect ID	Summary	Project	Module	Detected in Version
15466	An element atfer a stopped element can't be moved	Sky News	AB Roll Playlist	05.71.70
18709	One frame cued element. When it's finished, the next element won't be cued.	Sky News	AB Roll Playlist	05.75.20
17437	64 char name will be truncated after a restore	Sky News	Asset	05.73.50
20644	Channel Explorer it is possible to gang twice the same group (f&k + classical gang)		Channel Explorer	05.82.00
19712	Search for clips not in a PL (auto-refresh on)-> Clip doesn't disappear from the list once inserted in the PL		Database Explorer	05.80.30
17040	Search on all columns on existing clips -> it takes 20 sec to return a result		Database Explorer	05.73.10
20950	Move to online of Fill and Key PL -> Only the selected playlist is moved		Fill & Key	05.82.20
20914	Fill and Key Playlist Flatten to XT -> Link is lost between the two clips when the process is completed		Fill & Key	05.82.20
20923	Fill and Key playlist Once the Fill and Key files are restored, the type is kept but they are not linked anymore		Fill & Key	05.82.20
20926	F&K Clips Subclip F&K clips create only 1 asset		Fill & Key	05.82.20
21003	Ganged playlist send to default PL -> Both ganged clips are sent to one PL.		Gang Management	05.82.20
15030	Speed are desynchronised on ganged channel in shuttle mode/var mode		Gang Management	05.71.60
15049	Goto in/out does not work on ganged channel		Gang Management	05.71.60
20846	ESPN Worldcup Move or Duplicate LoRes Clip from one XL to another is not managed correctly	ESPN	HI-LO	05.64.60
13926	Blocks scheduled before tail of the Hires train create Lores clips even if the hires clip is not created		Ingest Scheduler	05.63.70
17302	When moving or copy EDL + clips (short or long), if a growig clip has been manually stopped, the display LSM/ID is not correct		lp Edit	05.73.50
16915	Mark in/out not reseted on preview player		lp Edit	05.72.90
15659	E2A : TLO information (NL/TC) are not updated when we are in trim mode on TLE		lp Edit	05.71.90
15894	E2A: When a clip following a black clip is removed, there is no color modification in the timeline		lp Edit	05.72.30



IP Director version 5.8 (v3)

Date: 09-sept-2010 Page: 12 File: IPDirector_release_note_V5.83.50.

16263	E2A No warning message when closing IPD		lp Edit	05.72.50
19476	IPEdit dissappears after inserting a clip and touching "window" key		Ip Edit	05.80.20
18929	E2A security zone If you make a commit, the orange blocks located before the security zone does not remain orange		Ip Edit	05.75.60
18955	Local clip moved to another server, the LSM/ID is not modified in the interface. The timeline needs to be reloaded to display the LSM/ID correctly		lp Edit	05.75.62
19143	E2A the swap is not executed, if I create a new clip		Ip Edit	05.75.62
6053	Drag and drop from player to timeline doesn't work with Osprey video board		Ip Edit	05.14.00
19790	Edit To Air - Master/Slave: An open ended growing clip used in Master Ip Edit is not replaced by the local clip on Slave when Syncis called. It is copied through SDTI Edit To Air - Master/Slave: Growing clip used on non redundant recorder are read through the SDTI network and not copied	С	lp Edit	05.80.30
19843	locally on slave		Ip Edit	05.80.40
20142	Replace If a post mark in offset GPI (or pre mark out offset gpi) is defined on clips defined with a speed different than 100%, GPI are not correctly played out		lp Edit	05.80.60
21015	Error message when we make some operations on offline clip> Convert to TL failed (system error : no clip found) 4101		lp Edit	05.82.30
21018	Could not load TL when trimming clip on offline clip		lp Edit	05.82.30
21041	Could not load TL when deleting offline clip		lp Edit	05.82.30
20859	IPLogger Protect Selected Logs is greyed out if a log is maximized		lpLogger	05.82.20
19164	Auto association of keywords to clip does not work when associating a file to a logsheet	Sky sports	lpLogger	05.75.50
20976	Selected profile at Timeline creation is not saved as default profile		Metadata	05.82.20
18559	Values are reset when importing EVS metadata if tags are not all provided	Sky News	Metadata	05.72.90
18557	In iNews, when moving a playing element, the playlist and the rundown are desynchronised.	Sky News	MOS	05.72.90
18078	iNews Delete element in play	Sky News	MOS	05.75.10
16730	XT_IN_TC_STR/XT_OUT_TC_STR/XT_DURATION_STR are modifed after a name update		Nearline	05.72.80
16999	Keyword (64 char) is lost when updating this file on a setup which runs with keywords in 12 char.		Nearline	05.73.10
14219	IPD detects only one file if we insert 2 files with the same name but different extension		Nearline	05.70.90
14275	Tag "clips" inserted twice in xml file but there is only 1 file associated to this xml file		Nearline	05.71.10
14423	Info in DB is not updated when we overwrite file+xml file with file+xml file with the same name (online NL)		Nearline	05.71.20
20938	VE Jump on Time does not work after a partial restore if job started 10 sec before the element has to pass on-air.		PlayList Management	05.82.20

Email :support@evs.tv Tel: +32 4 361 7000 Fax: +32 4 361 7099 IP Director



IP Director version 5.8 (v3)

Date: 09-sept-2010 Page: 13 File: IPDirector_release_note_V5.83.50.

17420	Copy Move Playlists - 2 users moving and copying from and to the same XTs : data loss	PlayList Management	05.73.60
20854	In browse mode, soft locks occur in loading the first 2-3 clips after loading a train.	Remote B	05.82.20
18093	Remote Installer - XML Unit Configuration window incorrect	Remote Installer	05.75.10
17529	Remote installer push the component 'bonjour' on a IP DRIVE workstation.	Remote Installer	05.73.70
15600	EVS INC Grabbed logs from the Remote Installer can't be unzipped	Remote Installer	05.64.20
17539	Playlist: Insert/Edit Tag: Swap audio back to "normal diagonal" after Swap audio "customised" changed in Mute OFF	Software player	05.73.70
17854	Software player in Playlist Panel - maximize panel window then associate Software Player: the panel flicks and the workstation appears as if it was blocked.	Software player	05.74.30
19852	Software can't go E/E in a train which overcomes 7FFFFFFF field numbering.	Software player	05.80.40
17772	Not possible to backup GC without out	XTAccess	05.74.20
21088	VTR Panel panel flicks when clips are being created	VTR Panel	05.82.40
21049	User plugin doesn't import groups	Remote Installer	05.82.20

5 Known limitations

5.1 Bin management

- Appearance/disappearance of clip elements is not considered as an update of a clip → bin rules are not run when adding/deleting a clip element to a clip.
- Bin rules are not kept from V4 to V5.8
- Bin rules are not kept from V5.6 to V5.8
- Maximum 20 bin rules at a time on your setup.

5.2 Nearline / software player

- No possible timecode restripe of nearline files.
- Software player does not support the field reference above 7FFFFFF.
- IPDirector does not support the fact that a file can be overwritten from Windows. For example, if a video file is overwritten by another one with the same name from the windows explorer, some side effects will be seen in the IPDirector (bad TC, bad metadata, ...).
- 1080P is not managed in IPD V5.8
- 3D is not managed in IPD V5.8
- Don't define a sub-directory to be managed by the IP Director if a parent directory of this sub-directory is already managed, otherwise the nearline management of this sub-directory will not work properly.
- A directory cannot be managed by 2 IP Director workgroups in master mode at the same time. Only one master nearline is supported, the other nearlines must be in slave mode.
- No drag and drop operation allowed from near line to near line to avoid lots of file re-wrap.
- If the user wants to copy files to an XFile drive, it's much faster to do it from the "media files" view because it does a windows copy rather than a file re-wrap.

5.3 Metadata

Predefined values in user fields (type combo) are not pushed in the keyword list.

5.4 Playlist

• Post-Roll: The post-roll mode is not synchronised between multicam and IPD. The post-roll mode will be lost (changed) if the channel configuration is changed (i.e.: passing from pgm/prv to 1 pgm mode will reset the post-roll information).

5.5 Ganged channels

- Synchronized channels: boundaries side effects not managed. If clip or train boundaries are not equal on the different synced players, this will lead to desynchronise if one boundary is reached on one of the players. Always be sure that you work with local trains otherwise you'll get a 3 seconds delay while in E/E
- Sometimes, it is possible to de-synchronize the channels (possibly using the jog wheel on the shuttle pro). It this happens, it is very easy to re-sync the channels hitting the "pause" button on the shuttle pro.

6 User's Guide and technical reference

6.1 The technical manual has been updated

- Technical manual :
 - → IPDirector_TechRef1_5.82_ENG_100715_web.pdf
 - → IPDirector_TechRef2_5.82_ENG_100715_web.pdf

6.2 The user manuals have been updated

Part1: General Workspace (Intro, MDI including metadata management & layout management, Channel Explorer, System Management)	IPDirector_userman_Part1_5.8_ENG_100630_web.pdf
Part2: Logging (IPLogger + Keyword Management)	IPDirector_userman_Part2_5.8_ENG_100630_web.pdf
Part3: Browsing (DB Explorer)	IPDirector_userman_Part3_5.8_ENG_100707_web.pdf
Part4: Ingest (VTR Panel, Ingest Scheduler, Recorder Panel)	IPDirector_userman_Part4_5.8_ENG_100630_web.pdf
Part 5: Playout - Player Control Panel (including Fill & Key section)	IPDirector_userman_Part5_5.8_ENG_100630_web.pdf
Part 6: Playout - Playlist Panel (including Fill and Key mgt)	IPDirector_userman_Part6_5.8_ENG_100702_web.pdf
Part 7: Editing - IPEdit	IPDirector_userman_Part7_5.8_ENG_100716_web.pdf
Part 8: Editing – EditToAir	IPDirector_userman_Part8_5.8_ENG_100716_web.pdf

6.3 Some application notes has been created, some updated

- Minimum PC requirements to install IP Director on non-EVS workstations
 - → Application note_PC_Hardware_5_08.pdf
- Database redundancy and maintenance
 - → Application note_External_SQL_Maintenance_v5.8.pdf
 - → Application note_External_SQL_Mirroring_v5.8.pdf
- DNS Server installation and configuration
 - → Application note_DNS_Configuration_4_04.pdf
- IP Director monitoring tool (from remote installer)



Date: 09-sept-2010 Page: 16 File: IPDirector_release_note_V5.83.50.

- → Application note_Monitoring_IPD_5.8.pdf
- IP Director nearline
 - → Application note_Nearline_config_5.8.pdf
- IP Director & Windows Integration
 - → Application_Note_Windows_Integration.pdf
- Time synchronisation between workstations using windows time service
 - → Application note_Time_sync.pdf

